

A0443834 - GLYCOL CONTACTOR INSPECTION - MAR 1999

1060-04

Canadian Natural Resources Limited
Production - Facilities Engineering
A0443834 Vertical 3 Phase Glycol Contactor Certificate
of Inspection

Content Date Range: 3/4/1999 to 3/4/1999

Vessel Integrity
Inspection Data

Open: 1/31/2007 Close:

Vital: Yes
Original: Yes
Confidential: No



00761964

Certificate of Inspection

BERKLEY PETROLEUM CORP.
1250, 202 - 6 AVENUE SW

CALGARY, AB
T2P 2R9

PREFERRED RE-INSP. INTERVAL: 2.00 Yr.
CRN: L5068.21

YEAR BUILT: 1999
VOLUME: 2 M3

HEATING SURFACE:
SURFACE AREA:
COMPANY CODE:

LOCATION: STOCK
DESCRIPTION: VERTICAL THREE PHASE GLYCOL CONTACTOR
MANUFACTURER: ALCO GAS & OIL PRODUCTION
SERIAL #: 99C-6099-01

PART	MAX. AUTHORIZED WORKING PRESSURE	MAX. TEMP	MIN. TEMP	Safety Valves			LOCATION
				VALVE ID	SETTING	CAPACITY	
CON	9928 KPA	52 C	-29 C	SV1			TO BE INSTALLED

OWNER INSTRUCTIONS/REMARKS:

CONTACT THE ABSA SAFETY CODES OFFICER BEFORE PLACING THE VESSEL/BOILER IN SERVICE.

VESSEL/BOILER TO BE INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT AND REGULATIONS.

VERIFY THAT VESSEL/BOILER IS PROTECTED BY A CODE PRESSURE RELIEF VALVE, OF ADEQUATE CAPACITY, SET AT NO MORE THAN MAXIMUM PRESSURE AUTHORIZED AND INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT & REGULATIONS.

Safety Codes Officer: SIMPSON, NORMIN

Signature: *N Simpson*

NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

The owner or person in charge shall report all accidents involving a boiler, pressure vessel or pressure piping system to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.