

4810-93 Street, Edmonton, Alberta T6E 5M4 Phone: (780) 469-2401 Fax: (780) 468-2422

Report No: 0

Client	Canadian Natural Resources Ltd.	Inspection Date	Jan 18, 2005	
Prov. Reg. #	AB 0517050	Inspection Type	Data	
Equipment Type	Vertical Glycol Contactor	Location	Calgary	
Tag/Equip.		LSD	AB Stock	
Status	In Service	Downhole LSD		
Manufacturer	Alco Gas & Oil Production	Area		
Serial Number	2004734001	Year Built	2004	
CRN#	P5021.2	Service		
Comp/Unit Id		Manway	None	
Nat.Board #		Coating		
Interim Insp'n		Interim Type		
Next Inspection	2005	Next Insp Type		
Length		Height	Height	
Volume		Client Reference		
Owner	Canadian Natural Resources Ltd.	RT	HT	
Foreman		RAE Job No.	04-214	
ABSA	Plant: Vessel: Process:	Special:	ASME	
History Log	ABSA Certificate of Inspection on file.			

Component SHELL 1					
MAWP	9925.0 kPa @ 54 °C			MDMT	
Material			Material Thickness		
Diameter		Length			
Corrosion Allowance					

General Observations


ABSA Certificate of Inspection on file.

Recommendations

1. To be installed.

Date Printed: Jan 8, 2015

Source: REMS



4810-93 Street, Edmonton, Alberta T6E 5M4
Phone: (780) 469-2401 Fax: (780) 468-2422

Report No: 0

Inspector: Reviewed By:

Source: REMS