Appendix 1: Mothballing Documentation Form

Vessel Description

A#, NB# or C#:	(A) 582644	**Date:**	March /2016
Serial #:	149-61-07	**Facility:**	Minehead / Hanlan
Vessel Description:	Dehydrator / contactor	**Vessel LSD:**	9-21-47-17

Please tick (only) one box that applies to this vessels situation:

☐	1) This vessel will remain out-of-service indefinitely. 2) This vessel will not be inspected until Operations decides to bring it back into service. 3) It is acceptable to inform the regulator (ABSA) that this vessel is out-of-service. Operations does not want to inspect the vessel after it is mothballed.
☒	1) This vessel is currently not being used. 2) Operations is unsure when it will be put back into service. 3) This vessel will be inspected at on its normal interval. There is no need to inform the regulator of any changes.

NOTES/COMMENTS:

- Filled contactor w/ 50:50 H_2O / Methanol
  + 1% R-2383 / + 1% RA-19
- Sucked out fluid + purged with N_2 left 100 kPA on vessel

Final Sign-Off

Print Name:	S. Gotean	**Sign Name:**	