		Equipment De	scription	
A#, NB# or C#:		C47862	Date:	Nov 27 2019
Serial #:		PE 4234	Facility:	B-97-4/94-11-4
Equipment Type:		Vessel ☐ Compressor ☐ Piping ☐ Other ☐	Equipment Number:	
Equipment Description:		Dehy Contactor	Equipment LSD:	B-97-H/94-H-4
	3) It is ac	cceptable to inform the Regulator the want to inspect the equipment after		
	2) Opera	quipment is currently not being use stions is unsure when it will be put be equipment will be inspected at on its rof any changes.	pack into service.	There is no need to inform the
Otes/Cor	2) Opera 3) This e regulator	ations is unsure when it will be put b	pack into service.	There is no need to inform the
·	2) Opera 3) This e regulator	ations is unsure when it will be put be	ack into service. s normal interval.	