



A0438939_Name plate_28Mar2012



Field Inspection Report



A0438939_Name plate_28Mar2012



A0438939_Inlet and Outlet piping_28Mar2012



A0438939_West End view_28Mar2012



A0438939_Burner and Stack assembly_28Mar2012

Field Inspection Report




A0438939_50,50 Reservoir tank_28Mar2012



A0438939_Surface rusting_28Mar2012



A0438939_Gasket leak on Stack_28Mar2012



A0438939_Ground cable secure_28Mar2012