

## Appendix 1: Mothballing Documentation Form

### Vessel Description

A#, NB# or C#:	① 417325	Date:	Dec 10/15
Serial #:	42116-52	Facility:	16-35-50-25
Vessel Description:	Line heater	Vessel LSD:	7-12-53-21 Boneyard

**Please tick (only) one box that applies to this vessels situation:**


<input type="checkbox"/>	<p>1) This vessel will remain out-of-service indefinitely.</p> <p>2) This vessel will not be inspected until Operations decides to bring it back into service.</p> <p>3) It is acceptable to inform the regulator (ABSA) that this vessel is out-of-service. Operations does not want to inspect the vessel after it is mothballed.</p>
--------------------------	---

<input checked="" type="checkbox"/>	<p>1) This vessel is currently not being used.</p> <p>2) Operations is unsure when it will be put back into service.</p> <p>3) This vessel will be inspected at on its normal interval. There is no need to inform the regulator of any changes.</p>
-------------------------------------	--

**NOTES/COMMENTS:**

Purged with N<sub>2</sub>, to 700 KPA pressure left on vessel/piping

### Final Sign-Off

Print Name:	Shilo Gotean	Sign Name:	
-------------	--------------	------------	--