

# DVR-FM-INT-000046 Appendix 1: Mothballing Documentation Form

Vessel Description			
A#, NB# or C#:	465654.	Date:	JAN 22 115
Serial #:	6339-401-1	Facility:	11-28-56-26 WS NY-28-KRYHART
Vessel Description:	LINE HEATER.	Vessel LSD:	11-28-56-26 WS

Please tick (only) one box that applies to this vessels situation:

- 1) This vessel will remain out-of-service indefinitely.
  - 2) This vessel will not be inspected until Operations decides to bring it back into service.
  - 3) It is acceptable to inform the regulator (ABSA) that this vessel is out-of-service. Operations does not want to inspect the vessel after it is mothballed.
- 
- 1) This vessel is currently not being used.
  - 2) Operations is unsure when it will be put back into service.
  - 3) This vessel will be inspected at on its normal interval. There is no need to inform the regulator of any changes.

**NOTES/COMMENTS:**

Clean / steamed w Fresh Heated water inhibited w/ 1% R-2383 and purged with Nz.  
Loft DRIANED

Final Sign-Off			
Print Name:	JASON KAPACH	Sign Name:	