

Certificate of Inspection Permit

FOURSTAR RESOURCES INC

501 24 AVENUE

NISKU, AB
T9E 8P2

COMPANY CODE:

DESCRIPTION: INDIRECT FIRED HEATER COIL

LOCATION: STOCK, NISKU

MANUFACTURER: FOURSTAR RESOURCES INC

Max. Inspection Interval: 1.00 Yr.

Year Built: 2018

CRN: Y8483.2

Serial #: 181048

Volume: 1.133 M3

Heating Surface: 55.18 M2

Surface Area:

PART	MAX. ALLOWABLE PRESSURE	MAX. TEMP	MIN. TEMP	Pressure Relief Valves			
				VALVE ID	SETTING	CAPACITY	LOCATION
COIL	7826 KPA	316 C	-29 C	SV1			TO BE INSTALLED


Terms and Conditions:

Owner must ensure an integrity assessment of this vessel/boiler is conducted after it is installed but prior to its operation. The integrity assessment shall be conducted by a person holding qualifications acceptable to the Administrator. Refer to ABSA publications AB-506, AB-512 and AB-515 for details about qualifications acceptable to the Administrator.

Owner must ensure this vessel/boiler is designed, constructed, installed, operated, maintained and decommissioned in accordance with the Safety Codes Act and Regulations.

Owner must ensure this vessel/boiler has overpressure protection that is a relief valve that meets the requirements of the ASME Code, or other means accepted by the Administrator expressly for this item.

Permit issued by: BENE, ZOLTAN D00009229

Signature: 

NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

An owner or vendor must notify the Administrator in writing when the pressure equipment identified on this certificate is sold or otherwise disposed of.

The owner or person in charge shall report all accidents involving Pressure Equipment to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.