

Pressure Vessel External Visual Inspection Report



Organization: Husky	Inspection Date: 28/06/2011
Plant: Southern Alberta	Equipment ID: 66047500
	Asset No: 66047500
	System: N/A
	Operating Unit: Wardlow Gas Plant

Background

Description:	SEPARATOR, 42" X 14", 1420 PSI
Asset Type:	Separator

Inspection

Inspector:	Forrest Lester	Company:	Husky Energy	Insulated:	N
-------------------	----------------	-----------------	--------------	-------------------	---

External Location Categories

Barrier Penetrations:		Damaged Insulation:		Vessel Supports:		Insulation Rings:	
------------------------------	--	----------------------------	--	-------------------------	--	--------------------------	--

Internal Location Categories

Erosion Zones:	
-----------------------	--

Inspection Comments

ID	Description	Condition	Location	NCR	Comments

Inspection Summary

A complete inspection was done to verify the integrity of this vessel VE and UT were used. No notable defects were found this vessel is recommended fit for continued service.

Pressure Vessel External Visual Inspection Report

Inspection Planning

Date of Inspection: _____ Date of last Inspection: _____ Date of Next Inspection: _____

The signature below certify that the above is a true report of the inspection / test of the equipment specified and consider fit for service until the date of next inspection.

Competent Inspector: _____ Report Generation Date: _____

Reviewed and Accepted by:

Next Inspection Date: _____

Approved by:

Signature: _____ Date: _____

Signature: _____ Date: _____