| Canadian Natural Mothballing Documentation Form | | | | | | |
|--|--|---|-----------|----------------------|---------------------------|--|
| Equipment Description | | | | | | |
| A#, NB# or C#: | | K0237.2 | | Date: | NOV27, 2019 WARDLOW | |
| Ser | ial #: | 2015.90 | Facility: | | WARDLOW 02-31-022-1/W4 | |
| Equipment Type: | | ☐ Piping ☐ Other | | Equipment Number: | V 100 | |
| | pment ription: | Inlet Separ | rator | Equipment LSD: | 02-31-022-1/104 | |
| Please tick (only) one box that applies to this vessels situation: | | | | | | |
| × | This equipment will remain out-of-service indefinitely. This equipment will not be inspected until Operations decides to bring it back into service. It is acceptable to inform the Regulator that this equipment is out-of-service. Operations does not want to inspect the equipment after it is mothballed. | | | | | |
| | 1) This ed | This equipment is currently not being used. | | | | |
| | 2) Operations is unsure when it will be put back into service. 3) This equipment will be inspected at on its normal interval. There is no need to inform the regulator of any changes. | | | | | |
| Notes/Cor | mments: | | | | | |
| | | | | | | |
| Final Sign-Off | | | | | | |
| Print I | Name: | Donna Darra (8) | | Name: | 4 Oh Miner | |