



Pressure Vessel Representative Inspection Report

TC-OVR-FM-INT-000016 Rev. 1

Inspection Year:	2019	District:	Red Deer
Inspection Interval:	5	Field:	Hillsdown 1029
Next Inspection:	2024	Service Environment:	<input checked="" type="checkbox"/> Sweet <input type="checkbox"/> Sour
Low Risk Equipment Type:	<input type="checkbox"/> Fuel Gas Scrubber <input type="checkbox"/> Indirect Fired Heater Coil <input type="checkbox"/> Methanol Vessels		
	<input type="checkbox"/> Air Cooled Heat Exchanger <input checked="" type="checkbox"/> Well-Site Separator		

Statement on Representative Inspection in the CNRL Owner-User Program:

The Regulatory Inspection of the following vessel(s) has been conducted by Representative Inspection. Review and approval of the suitability of this vessel for Representative Inspection was conducted by a CNRL Asset Integrity representative and has been documented in accordance with CNRL's Owner User Program.

The following vessels have undergone a direct, physical inspection and represent a minimum of 10% of the vessels (of this type) in the field:

A0221712, A2996390, A2806105, A2996431, A3070545, A0454817, A0190533

The following vessels are substantially the same in terms of geometry, design, construction, conditions of service and service location such that they are subject to substantially the same degradation mechanisms and rates. These vessels represent a maximum amount of 90% of the vessels (of this type) in the field:

A0433699, A2996383, A0226182, A0200596, A2789699, A2917467, A0418024, A2917773, A2979519, A3017863, A3127193, A2708056, A2708063, A2757627, A2847135, A2918546, A2941950, A2996448, A2996493, A3017344, A0433701, A0156756, A2917766, A0437365, A3143351, A2979502, A2926504, A3035731, A0535355, A0472206, A0543686, A2996479, A3127100, A0552758, A0532067, A3054734, A2708386, A3017856, A3174281, A2682170, A3017069

*Should be A2917546

CNRL Asset Integrity Representative (print)	Leanne Dobson	Date: 14 May, 2019
CNRL Asset Integrity Representative (signature)		Date: 14 May, 2019
Provincial Inspector License # (ABSA/TSASK)	Ryan Booth A-95265	
(I am in full agreement that representative inspection is valid)		May 17, 2019