



Date of Inspection

Field Name:	WAPITI		Facility Location:	8-36-68-9wb	
Prov. Reg.# A Number, S Number, BC Number or C#	(A) 2922696		Equipment Type (e.g. treater, separator, scrubber)	SEPARATOR	
Design Pressure (MAWP)	1440 PSI		Name of Manufacturer	RJV	
Year Built	1994	Serial Number	2691	CRN	M 2801.2
Vessel Status: circle	In Operation	Not In Operation	Comp./Unit #(e.g. 1408)		
Vessel Service: circle	Sweet	Sour	Tag/Equip. #(e.g. V-101)		
Vessel Access: circle	Manway	Hand Hole	Size of Access:		
PSV TAG#.	WAP6833	Manufacturer	CONSOLIDATED	Set Pressure	1440 PSI
Type/Model	1997	Serial #	9400 675	Size (in x out)	1 1/2" x 2"
Date of Service	9/20/2014	Capacity	10686 SCFM	Units	
Code Symbol Stamp		Service Co.	KINGS		

Check	Item	Comments	Checked by
Vessel Supports	Vessel bolted down	ESSE	SB.
	Inspection hole in skirt		
	Ladders/Platforms are secure		SB.
Bulges, dents or blisters on vessel	No evidence of external deformities on the vessel or piping system.	EXTREMELY RUSTY	SB.
Ground Wire	Ground wire is in place		SB.
PRV Condition	Sealed with a lead seal		SB.
	Set pressure not to exceed MAWP of Pressure Vessel		SB.
	Installed in a vertical position		SB.
	Block valves locked open	N/A.	
	Drain hole is visible and not plugged		SB.

Check	Item	Comments	Checked by
	Discharge pipe size not smaller than inlet of valve		SB
	Valve discharge braced or not in an area that may be dangerous to personnel		SB
	Block valves not permitted on power boilers or heaters		
	Service Date not to exceed 5 years (state last service date)	9/20/2014	SR
Insulation	Cladding in good condition and caulking adequate	BUILDING IS IN POOR CONDITION	SB
Piping Inspection	Provision for adequate support		
	No evidence of leakage		SB
	Proper alignment to ensure no undue strain on the system		SB
	Proper rating for service conditions		SB
New Equipment Data Package (Confirm Controlled Documents have been supplied to CNRL)	Manufacturers Data Report for Pressure Vessels	NO	
	Jurisdictional - Construction Data Report for Piping systems (AB-83, BC 1329)	NO	
	Certificate of Inspection Permit Issued (AB, BC, SASK)	NO	
	P & I.D.'s - As built verified	NO	
	Quality Management documents	NO	
Name Plate	Is the nameplate correct?		SB
	Is the CRN valid for the province of installation?		SB

The field consultant shall provide all the required information to the Asset Integrity Group prior to startup. All requested information shall be sent to the area mailbox.

ADDITIONAL COMMENTS:

Authorized Owners Inspector:

STEVIE BRODIE 

Contact Number:

780 831 5189

CNRL Asset Integrity Representative:

Contact Number: