

## Appendix 1: Mothballing Documentation Form

### Vessel Description

A#, NB# or C#:	A 191862	Date:	
Serial #:	81-7900A	Facility:	Excess Oil Battery
Vessel Description:	Horizontal Rectifier	Vessel LSD:	10/08-98-11W6m

**Please tick (only) one box that applies to this vessels situation:**



- 1) This vessel will remain out-of-service indefinitely.
- 2) This vessel will not be inspected until Operations decides to bring it back into service.
- 3) It is acceptable to inform the regulator (ABSA) that this vessel is out-of-service. Operations does not want to inspect the vessel after it is mothballed.



- 1) This vessel is currently not being used.
- 2) Operations is unsure when it will be put back into service.
- 3) This vessel will be inspected at on its normal interval. There is no need to inform the regulator of any changes.

NOTES/COMMENTS:

### Final Sign-Off

Print Name:

Rick Bosch

Sign Name:

