

Return to:

Canadian Natural Resources Ltd. – Integrity Group (Anthony Merle)

Suite 2500, 855 – 2nd Street SW, Calgary, AB T2P 4J8

Phone: (403) 517-7301 Fax: (403) 517-7366

anthony.merle@cnrl.com

Pressure Equipment Field Inspection Report

CNRL Business District (e.g. NE Gas, St. Albert, Bonnyville, Edson)	MEDICINE HAT WEST		Date of Insp.	OCT 15/10 IRIS NDT	
Prov. Reg.# (e.g. A#, RAE#, C#)	A# 2710237		Location (Field Name)	5-14-18-10WY	
Equipment Type (e.g. treater, separator, scrubber)	TREATER		LSD	RALSTON	
Tag/Equip. # (e.g. V-101)	5600-V1		Comp./Unit # (e.g. 1408)		
Vessel Status:	In Operation Dec 01/2010	Not In Operation	Job #	5°F @ 75PSI	
Fabricator	NATCO	Serial #	L-8-325	MAWP/Temp	75PSI
CRN#	H-0995.2	Shell Mat'l	516-70	Shell Thick.	9.5mm
Corr. All.		Head Mat'l	516-70	Head Thick.	16.9 FT END 15.2 (Cathosol)
Diameter	8 FT	Length	20 FT	Height	
Year Built	3-1991	Next Insp.		RT	4
Service	SOOR	Manway	3	HT	
PSV #.					
Mfg.	CONSOLIDATED	Serial #	76565-N	Insp. Type	VE VI UT
Type/Model	1905-JC/YSG	Capacity	2271	Coating	YES
Date of Service	OCT 15/10	Next Service		Set Pressure	75PSI
				Size	2X3/10
				Service Co.	TARTAN

Report # 8120

Observations:

Recommendations: MANWAY + FIRE TUBE opening - Coating Repairs By AR-TECH NOV 3/10
AS PER IRIS NDT INSPECTION.

Inspector: JERRY DOENK

Reviewed By:

Contact Number: 403-382-7908