



PRV INSPECTION AND TEST REPORT

BRANCH: Fort St John

UVL ID#: 20061F

Work Order: 308183

Customer PO#:

Customer: CANADIAN NATURAL RESOURCES LIMITED

Date: 3/16/2012

Facility: MINK

LSD: b-033-A/94-A-15

PSV Location: SEPARATOR FLARE GAS

A#: A2525265

Vessel SN:

Cust Id:

Cust. Ref.:

Valve PO:

PO Line#:

Cust WO#:

Cust AFE#:

Cost Centre #:

VALVE DATA

Man.: MERCER

Model: 81-34251V13G11

Serial: 742472

Seat: Soft

Conn: Threaded

Inlet: 1.5" MNPT

Orifice: G

Outlet: 2" FNPT

Set Pres: 285 PSI

Back Press: 0 PSI

Cold/Diff Set: PSI

Temp: 70°F

Cap: 2366 SCFM

Lift Lever:

Cap Assembly: Closed

Code Symbol: UV

CRN#: 0G8841.5C

CUSTOMER INSTRUCTIONS

Instructions: Sold New Valve

Pretest Required?

Reset Required?

Replaces UVL ID#: 5737V

Replaces Serial #: 57282

Replaces Cust ID#:

RESET INFO: New Pressure:

New Cold/Diff:

New Capacity:

New Model:

CONDITION AS RECEIVED

Visual Condition: NEW

Data Plate Condition: Replace

Date of last service: N/A

Seal Condition: Top: Intact

Bottom: N/A

Insignia: MVC

Fittings Attached: Inlet: Outlet:

Inlet: NEW

Inlet Plugged:

Outlet: NEW

Outlet Plugged:

Initial Insp. Signoff: Tara Stones

PRETEST 1

Simmer: Set Press: Reseat: Leakage: Test gauge:
Tested by: Pretest comments:

PRETEST 2

Simmer: Set Press: Reseat: Leakage: Test gauge:
Tested by: Pretest comments:

Table with columns: ITEM, CLEAN, OILY, RUSTY, CARBON, OTHER, COMMENTS, OK / REPLACE, REPLACED?, REPAIRS PERFORMED. Rows include DISC, NOZZLE, CAP-LEVER ASSY, COMP SCREW and LOCKNUT, SPRING and BUTTONS, SPINDLE / STEM, STEM RETAINER, DISC HOLDER, GUIDE / UPPER RING, LOWER RING, RING PIN(S), BELLOWS, GASKET / SEALS, CONNECTION ENDS, OTHER.

Disc: MIN= ACT= Nozzle: : ACT= Spring Number: 05-007

Comments:

Disassembly: Inspection: BRAD WATSON Reassembly:

FINAL TEST:

Test Medium: Air Simmer: 282 PSI Set Pressure: 285 PSI
Reseat: 254 PSI Leakage Acceptable: B.P. Test: 60 PSI
ADJ. RING SETTING (NOTCHES): Upper: N/A Lower: N/A Test Gauge FSJ 1&2 Set Press Def: POP
Tested by: Harley Anderson

FINAL INSPECTION:

SEAL: Top: Bottom: End Protectors Installed: Painted: Palletized: Ship Container: Flex Gaskets Supplied:
Final Inspection: Tara Stones Customer Inspection
Comments: PREVIOUSLY @ 150 PSI, NEW CAPACITY AS PER MERCER SLOPE; ADD A#