



Canadian Natural

Pressure Vessel External Visual Inspection Report

Report #: **EV_A 0433615_nov2011**
Inspection Date: **Nov 15, 2011**
Inspection Company: **Lance Inspections Inc.**
Inspector: **Lance Smith**

LSD: **11-28-74-10 w6m
(central)**

Description: **Horizontal Inlet Separator**

UTS Drawing#: **1**

Item	N/A	Condition	Comment	NCR	Action Item Integrity	Action Item Maintenance
Nameplate		O.K				
Foundation and Supports		O.K				
Anchor Bolts		O.K				
Grounding		O.K				
Insulation Condition	x					
PSV		O.K				
Shell Heads and Nozzles		O.K				
Metal Surfaces (Paint)		O.K				
Aux Equipment	x					
Cathodic Protection	x					
Alignment		O.K				
Flange Connections		O.K				
Pressure Gauge		O.K	0 to 7000 kPa			
Temperature Gauge		O.K	-20 to 120°C			
Sight Glass		O.K				
Ladder / Platform		O.K				
Leaks		O.K				
Piping from Vessel		O.K				
Previous UT Survey		O.K				

External Visual Observations:

Recommendations:

None.

This vessel and associated components appear fit for service at this time.

INSPECTED BY
LANCE SMITH
API 510 #28860