

Mothballing and Rendering Safe Documentation Form TC-OVR-FM-INT-000046_2

Equipment Description			
Jur#:	A) 232155	Date:	Nou 10,2021
Serial #:		Facility:	NOU 10,2021 ENDIANG.
Equipment Type:	Vessel Piping Tank Other	Equipment Number:	
Equipment Description:	SEPARATOR.	Equipment LSD/NTS:	10-29-34-15 WY
If mothballing or rendering safe multiple pieces of equipment insert "See Attached List"			
Mothballing for Temporary Suspension of Operation (<12 months)			
1) The equipment will remain out-of-service for <u>less than 12 months</u>			
	2) Mothballing required actions will be carried out as per Section 4 of <u>TC-OVR-PRO-INT-000021</u>		
	3) Equipment Inspection and PRD servicing not required but maintained at given frequencies		
	4) Equipment status remains "in-service", form required in IDMS to document layup process		
Mothballing for Temporary Suspension of Operation (>12 months)			
	The equipment will remain out-of-service for more than 12 months		
	2) Mothballing required actions will be carried out as per Section 5 of TC-OVR-PRO-INT-000021		
	3) Equipment Inspection and PRD servicing is required when returned to active operation		
	4) Equipment status changed to "out of service", form is required in IDMS to track changes		
Mothballing for Surplus (To be relocated)			
	1) The equipment will be allocated for surplus based on the Shut-In Facility Management Guideline - Guide		
	for transitioning Active Facility to Shut-in Status (Field OPS)		
	2) Mothballing required actions will be carried out as per Section 5 of TC-OVR-PRO-INT-000021		
	3) Equipment status changed to "mothballed", form is required in IDMS to track changes		
Rendering Safe for Decommissioning			
	The equipment has been selected for decommissioning as per the Shut-In Facility Management Guideline -		
	Guide for transitioning Active Facility to Shut-in Status (Field OPS)		
	2) Rendering Safe required actions will be carried out as per Section 7 of TC-OVR-PRO-INT-000021 and the		
	Shut-In Facility Management Guideline – Site Clean-up Checklist		
	3) Equipment status changed to "out of service" 3)		
- No FGS			
	SEPARATOR PACKAGE BYPASSED, WELL TIED DIRECT		
Final Sign-off			
Print Name:	EO IMBERY		Name: Shaly