

Mothballing Documentation Form

Equipment Description						
A#, NB# or C#:		A0247572		Date:	2019 October 12, 2020	
Serial #:		28716 A		Facility:	04-18-32-22w4	
Equipment Type:		☑ Vessel □ Piping	Compress	sor	Equipment Number:	3920
Equipment Description:		Bullet			Equipment LSD:	04-18-32-22w4
Please tick (only) one box that applies to this vessels situation:						
V	 This equipment will remain out-of-service indefinitely. This equipment will not be inspected until Operations decides to bring it back into service. It is acceptable to inform the Regulator that this equipment is out-of-service. Operations does not want to inspect the equipment after it is mothballed. 					
	 This equipment is currently not being used. Operations is unsure when it will be put back into service. 3) This equipment will be inspected at on its normal interval. There is no need to inform the regulator of any changes. 					
Notes/Comments: Vessel was drained completely. Vessel was left in a no pressure state. Facility is blinded @ the perimeters, Drain lines have been blinded.						
Final Sign-Off						
Print Name:		Troy Normand		Sign	Name:	hap d.