



5155

RAE Inspection Service (1978) Ltd.
 #111, 4808 - 87 Street, Edmonton, Alberta, Canada T8E 5W3
 Telephone (780) 489-2401, Facsimile (780) 466-2422

Above-Ground Storage Tank Form

Above-Ground Storage Tank Identification

Date: 23/07/12 Page 1 of 2

Owner	Canadian Natural Resources	
Production Area	<input type="checkbox"/> Western B.C. <input checked="" type="checkbox"/> Central <input type="checkbox"/> North/Eastern <input type="checkbox"/> Southern <input type="checkbox"/> Heavy Oil/Sask. <input type="checkbox"/>	
LSD & Location	3-16-77-1 W5 McMillan	
Description	Blow Down Tank	Skid Mounted <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Manufacturer	R.S.V.	Internally Coated <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Capacity	100 BBL	

Tank Static Data

Tag Number	5155	Serial Number	5155
Shell Material	STEEL	Thickness	
Floor Material	"	Thickness	
Deck Material (Roof)	"	Thickness	
Corrosion Allowance		Diameter	
Year Built	1998	Height	

Other Data

Secondary Containment	<input type="checkbox"/> Dirt <input type="checkbox"/> Lining <input type="checkbox"/> Sand <input type="checkbox"/> None <input checked="" type="checkbox"/> Other:
Service	<input type="checkbox"/> Oil <input type="checkbox"/> Produced Water <input type="checkbox"/> Sour <input type="checkbox"/> Condensate <input type="checkbox"/> Water <input type="checkbox"/> Pop Tank <input checked="" type="checkbox"/> Other: Blow Down

Comments Tank Has Secondary Containment

R# 12026