



**APPLUS-RTD**  
 EDMONTON, ALBERTA,  
 CANADA T6P 1N5  
 TEL: (780) 440-6600 FAX: (780) 440-2538

**GENERAL NDE REPORT**

Date November 22, 2012 Page 1 of 2  
 RTD Job #: 10.112250  
 RTD Dep. #: Grande Prairie

Client: C.N.R.L  
 Address: Grande Prairie, AB  
 W.O.#: \_\_\_\_\_  
 Client Rep.: Craig Liba

LSD: L.S.D. 13-20-96-09 W6M  
 Location: North Hamburg  
 Procedure: RTD-MT- 001 rev 003  
 Code: API 12F

Description: MT inspection carried out on 1000BBL Tank C50088  
 Surface Condition:  Weldment  Machined  Painted  
 Ground  Sandblasted  Other Surface Temp (C°):  < 5  > 5  < 60  > 60

**MAGNETIC PARTICLE INSPECTION**

Equipment Type:  Yoke  Bench Asset No.: 11089 Calibration Due Date: 01-03-13  
 Blacklight: Intensity Check: \_\_\_\_\_  $\mu\text{W}/\text{cm}^2$  Asset No.: 12754 Calibration Due Date: 01-03-13  
 Method:  A/C  D/C Type:  Continuous  Residual Power Supply:  120 V  Battery  Natural  
 Type:  Dry Powder: Colour; \_\_\_\_\_ Wet:  Black and White  Fluorescent  
 Product Manufacturer: Magna Flux Product Identification Code: \_\_\_\_\_

**INSPECTION DETAILS**

Scope: **Weld repairs inspected with Magnetic Particle Inspection method**

Results: **No cracks or relevant indications present within the welds inspected.**


Technician: Dellas Wiedman CGSB /ASNT/SNT Level: II Start Time: \_\_\_\_\_ Stop Time: \_\_\_\_\_ ST \_\_\_\_\_ OT \_\_\_\_\_  
 Signature: Method: MT Unit: \_\_\_\_\_ Km: \_\_\_\_\_ Travel Time: \_\_\_\_\_  
 Assistant: \_\_\_\_\_ CGSB /ASNT/SNT Level: \_\_\_\_\_  Subsistence required  OT Meal  
 Client Signature: \_\_\_\_\_ Consumables: \_\_\_\_\_

\*Results are an interpretation of the inspection method, not a guarantee. Client signature indicates acceptance of report, results and applicable charges.



LSD

Overview Tank



Data plate

Over view of patched areas