

Appendix 1: Mothballing Documentation Form

Vessel Description

A#, NB# or C#:		Date:	May 5, 2020
Serial #:		Facility:	2-30-71-26W5M
Vessel Description:	Slop Tank T701	Vessel LSD:	2-30-71-26W5M

Please tick (only) one box that applies to this vessels situation:

<input checked="" type="checkbox"/>	1) This vessel will remain out-of-service indefinitely.
<input checked="" type="checkbox"/>	2) This vessel will not be inspected until Operations decides to bring it back into service.
	3) It is acceptable to inform the regulator (ABSA) that this vessel is out-of-service. Operations does not want to inspect the vessel after it is mothballed.

	1) This piping is currently not being used.
	2) Operations is unsure when it will be put back into service.
	3) This vessel will be inspected at on its normal interval. There is no need to inform the regulator of any changes.

- **NOTES/COMMENTS: Tank is blinded, fully washed and air purged. Tank is internally coated so no inhibitor in wash required**

Final Sign-Off

Print Name:	Lee Palmer	Sign Name:	
--------------------	-------------------	-------------------	--

