

PRV INSPECTION AND TEST REPORT

BRANCH: Grande Prairie UVL ID#: 17801G

Work Order: 523928 Customer PO#:

Customer Facility: A#: Cust. Ref.: Cust. WO#:	CANADIAN NATU POUCE COUPE : A463670		JRCES I	LIMITED LSD: Vessel Valve Cust Al	SN: PO:	-079-12W	/6M			Date: 05/06/2 PSV Locati Cust PO LINI Cost Centr	on: SEPA Id: E#:	RATOR				
Man.: M	IERCER	Mo	odel: {	81 ₋ 17151	T17G21S	VA	LVE DA		al : 133140				Seat: P0	np.		
Conn. To the set Press. 14 Lift Lever	Back Cap As	T				Orifice: E Ou		utlet: 1" FNPT Temp:		Cap: 4956 SCFM CRN#: 0G8841.5C						
					CU	STOME	R INSTE	RUC.	TIONS							
Instructions: Pretest, Service, and Test Replaces UVL ID#: Replace RESET INFO: New Pressure:					es Valve Serial# : New Cold/Diff Set:				Pretest Required? Replaces Valve Cust ID# New Capacity:				Reset Required?			
						NDITIO	NASR	FCF	-							
Visual Conditior Seal Condition: Inlet: Oily	n: Fair <i>Top:</i> Intac <i>Inlet Plug</i> g		В	Plate Con ottom: N	dition: I/A	ОК	Insignia	a:	Date of	of last service: Fittings Attac Insp. Signoff:	ched:	6/10 <i>Inlet:</i> ico Santo		Outlet:		
	PRETEST 1															
	136 PSI Natt Leslie	Set Press: Pretest (37 PSI nts:		Reseat:	1271 P	'SI	Leakage:	10+ BPM	Test (Gauge:	10K-1/5			
Simmer: Tested By:	PSI	Set Press:		SI nts:		PR Reseat:	PSI	2	Leakage:	ВРМ	Test (Gauge:				
					СО	MPONE	NTS IN	SPE	CTION							
ITEM			CLEAN	OILY	RUSTY	CARBON	OTHER	CON	IMENTS	OK / REPLAC	ED REP	PLACED?	REPAIRS PERF	ORMED		
DISC										OK			Clean			
NOZZLE										OK			Clean			
CAP-LEVER	ASSY									OK			Clean			
COMP SCRE	EW and LOCKNUT			$\overline{\mathbf{A}}$						OK			Clean			
SPRING and				$\overline{\Delta}$						OK			Clean			
SPINDLE / S								N/A								
STEM RETA								N/A								
DISC HOLDE								N/A	١							
GUIDE / UPF				$\overline{\mathbf{A}}$						OK			Clean			
LOWER RIN								N/A								
RING PIN(S)								N/A								
BELLOWS GASKET / SI	EALC							N/A Wo		REPLACE	=		Donland			
CONNECTIO								- 770	1111	OK	=		Replaced Clean			
OTHER	DIV LINDO									OK .			Olean			
DISC: :	SUB	ACT - N/A			NOZZLE	 : МIN -	SOFT		Δ.	CT - N/A		NUMBE	R : 05-017	,		
Comments:	002	A01 - 107	•		NOZZZZ	. 11114 -			A	77 - 1477		NOMBL	-rt. 00 017			
Disassembly:	Derrick V	Valpole			Inspection	on: [Derrick Wa	alpole	:	Reassem	bly:	Derrick	Walpole			
						FIN	IAL TES	ST								
Test Medium: Reseat: ADJ. RING SET ^T Tested by:	Air 1264 PSI TING (NOTCHES):	Upper	Simn Leak	age:	1438 0 BF <i>Lo</i>	PSI PM	I/A		Set Pressure B.P. Test: Test Gauge:	e: 1440 PSI 60 PSI 10K-1/5		old/Diff S				
SEAL: Top Final Inspectior Comments:		ш	End Prote	ectors Inst	alled: mer Inspec	✓ Pa	INSPEC		N: Palletized:	Ship Con	tainer:	✓ Flex	x Gaskets Supp	lied:		