Appendix 1: Mothballing Documentation Form				
Vessel Description				
A#, NB# or C#:	A62266	0	Date:	April 26 2020
Serial #:	12757		Facility:	16-13-65-3
Vessel Description:	3 phase sep		Vessel LSD:	16-13-65-3
Please tick (only) one box that applies to this vessels situation:				
This vessel will remain out-of-service indefinitely.				
2) This vessel will not be inspected until Operations decides to bring it back into service. 3) It is acceptable to inform the regulator (ABSA) that this vessel is out-of-service. Operations does not want to inspect the vessel after it is mothballed.				
1) This vessel is currently not being used.				
2) Operations is unsure when it will be put back into service.				
3) This vessel will be inspected at on its normal interval. There is no need to inform the regulator of any changes.				
NOTES/COMMENTS:				
Well shut at highline and casing, ESD shut in building, Liquids blown to tank, PL pigged out, Tank MT.				
F: 10: 0"				
	Fina	l Sign-Off		
Print Name:	Kris Durga	Sign N	lame:	Kru Durga