



Mothballing Documentation Form

Equipment Description

A# NB# or C#:	567367	Date:	Dec. 6 2016
Serial #:	R4562.213 S. - 2010	Facility:	13-25-66-10W6
Equipment Type:	<input checked="" type="checkbox"/> Vessel <input type="checkbox"/> Compressor <input type="checkbox"/> Piping <input type="checkbox"/> Other _____	Equipment Number:	
Equipment Description:	24" Separator	Equipment LSD:	13-25-66-10W6

Please tick (only) one box that applies to this vessels situation:

- ☒ 1) This equipment will remain out-of-service indefinitely.
- ☒ 2) This equipment will not be inspected until Operations decides to bring it back into service.
- 3) It is acceptable to inform the Regulator that this equipment is out-of-service. Operations does not want to inspect the equipment after it is mothballed.

- ☒ 1) This equipment is currently not being used.
- ☒ 2) Operations is unsure when it will be put back into service.
- 3) This equipment will be inspected at on its normal interval. There is no need to inform the regulator of any changes.

Notes/Comments:


Vessel Found drained and depressured.
ON Dec 6, 2016

Final Sign-Off

Print Name:

Mike Dube

Sign Name:



#1

W
HT
RTI

{U}

CERTIFIED BY
Silverado Oilfield Ventures Ltd.
Red Deer AB 403-340-1900

24" SEPARATOR

MAWP INT. 1480PSI EXT. AT 100°F

MDMT -20°F AT 1480PSI

SERIAL NO. S-2010 YEAR BUILT 2003

CRN R4562.213

Ⓐ 567367

1534