Appe	endix 1: Mothballi	ing Documen	tation Form	
	Vessel	Description		
A#, NB# or C#:	(A) 576033	Date:	June 13/6	
Serial #:	11118	Facility:	5-19-55-2125	
/essel Description:	Segerator	Vessel LSD:	6-19-55-2125	
lease tick (only) on	e box that applies to this ve	essels situation:		
	ilian frantisia da distribuita da distribuita da distribuita da distribuita da distribuita da distribuita da d			
1) This ve	essel will remain out-of-servic	e indefinitely.	-	
2) This ve	2) This vessel will not be inspected until Operations decides to bring it back into service.			
3) It is 22	centable to inform the regulat	tor (ARSA) that this ye	esal is out-of-service. Operations	
8 1 1	3) It is acceptable to inform the regulator (ABSA) that this vessel is out-of-service. Operations does not want to inspect the vessel after it is mothballed.			
	,			
1) This ve	essel is currently not being us	sed.		
2) Operat	2) Operations is unsure when it will be put back into service.			
	3) This vessel will be inspected at on its normal interval. There is no need to inform the regulator of any changes.			
	*.			
OTES/COMMENTS				
- Filled w	ith 50:50 Hz Mat	0 + 1% R-23	383	
	MI	4 1 14 811	-10	
1				
- Let sit	for minimum	24hrs and	purged with No	
		A	/	
	100 KPA	left on Ves	ssel.	
	Fina	l Sign-Off		
Print Name:	Shilo Crotean	Sign Name:		
1	Dh. 10 (rotean)	oignieumo.		