## Pressure Vessel External Inspection Checklist



Inspector Wayne Gerber (Probe)				7/16/2009	
Equipment Unit #28100 Separator A # 465571				2001-6653-01 P 6133.2	
	ОК	N/A	NOK		Comments
Shell	<b>✓</b>				
Head (Upper, North or West)	<b>✓</b>				
Head (Lower, South or East)	<b>✓</b>				
Alignment	<b>✓</b>				
Insulation/Paint	<b>✓</b>				
Saddles and Repads (Weep Holes)	<b>✓</b>				
Supports	<b>✓</b>				
Nozzles/Manway	<b>✓</b>				
Flanges (Evidence of Leakage)			<b>✓</b>	1/2" inspe	ection flange off and taped over
PSV	<b>✓</b>				
Foundation	<b>✓</b>				
Foundation Bolts	<b>✓</b>				
Grounding Cable	<b>✓</b>				
Appertunances	<b>✓</b>				
Adjacent Piping	<b>✓</b>				
Ladder/Stairway		<b>✓</b>			
Catwalk		<b>✓</b>			
				PA	
Notes:				05,	lor Lo