



Pressure Vessel
External Visual
Inspection Report

Report #: EV_A 3113855_nov2011

Inspection Date: Nov 14, 2011

Inspection Company: Lance Inspections Inc.

Inspector: Lance Smith

LSD: 04-27-74-10 w6m

Description: Line Heater

UTS Drawing#: 2

Item	N/A	Condition	Comment	NCR	Action Item Integrity	Action Item Maintenance
Nameplate		O.K				
Foundation and Supports		O.K				
Anchor Bolts		O.K				
Grounding		O.K				
Insulation Condition		O.K				
PSV		O.K				
Shell Heads and Nozzles		O.K				
Metal Surfaces (Paint)		O.K				
Aux Equipment	X					
Cathodic Protection	X					
Alignment		O.K				
Flange Connections		O.K				
Pressure Gauge		O.K	electronic			
Temperature Gauge		O.K	-20 to 120°C			
Sight Glass	X					
Ladder / Platform		O.K				
Leaks		O.K				
Piping from Vessel		O.K				
Previous UT Survey		O.K				

External Visual Observations:

Recommendations:

None

This vessel and associated components appear fit for service at this time.

INSPECTED BY
LANCE SMITH
API 510 #28860