



Pressure Vessel
External Visual
Inspection Report

Report #: **EV_A 0439083_nov2011**
Inspection Date: **Nov 15, 2011**
Inspection Company: **Lance Inspections Inc.**
Inspector: **Lance Smith**

LSD: 03-29-74-10 w6m

Description: **Line Heater**

UTS Drawing#: **2**

Item	N/A	Condition	Comment	NCR	Action Item Integrity	Action Item Maintenance
Nameplate		O.K				
Foundation and Supports		O.K				
Anchor Bolts		O.K				
Grounding		O.K				
Insulation Condition		O.K				
PSV	X					
Shell Heads and Nozzles		O.K				
Metal Surfaces (Paint)		O.K				
Aux Equipment	X					
Cathodic Protection	X					
Alignment		O.K				
Flange Connections		O.K				
Pressure Gauge	X					
Temperature Gauge		O.K	-20 to 120°C			
Sight Glass	X					
Ladder / Platform	X					
Leaks		O.K				
Piping from Vessel		O.K				
Previous UT Survey		O.K				

External Visual Observations:

Recommendations:

None.

This vessel and associated components appear fit for service at this time.

INSPECTED BY
LANCE SMITH
API 510 #28860