

Mountain West Services Ltd.

#3, 14 Thevenaz Industrial Trail, Sylvan Lake, AB T4S 2J5

Field Inspection Report - CNRL 478629_6/5/2011_VT_External

Vessel Number	478629	Vessel Name	LINE HEATER	Province	Alberta
District	WEST COUNTY	LSD	09-02-075-11W6	Location	VALHALLA
Method	VT	Access	External	Cleaning	Good
Inspection Date	6/5/2011	Inspection Interval	60	Next Inspection	6/5/2016
CRN	B-60.21375789T1	Skid Number	SKID0220	Service	
Manway	NO	Coating	False	Status	In Service
MAWP (PSI)	3375	MAWP (Kpa)	23269.95		
MAWT (F)	93.33	MAWT (C)	200	Outstanding NCRS	0

General

Safety Valves

PSV NON-CODE Shell side. Set pressure 10 PSI / 0 KPa. Capacity: 0 SCFM / 0 m3/min.

PSV NON-CODE Coil2 side. Set pressure 1563 PSI / 0 KPa. Capacity: 0 SCFM / 0 m3/min.


PSV NON-CODE Coil1 side. Set pressure 3375 PSI / 0 KPa. Capacity: 0 SCFM / 0 m3/min.

External

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical bonding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection.

Recommendations

INSPECTOR : I have witnessed/done the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate. I certify that the status of the Pressure equipment detailed here is:

Suitable to be returned to Service	Yes	Repairs complete (AB-40 attached)	N/A
Repairs are still required	No	Suggested Inspection interval	60
Warren Fast Inspector			6/7/2011 Date

