



Pressure Vessel External Visual Inspection Report

Report #: **EV_A 492937_nov2011**
 Inspection Date: **Nov 17, 2011**
 Inspection Company: **Lance Inspections Inc.**
 Inspector: **Lance Smith**

LSD: 08-11-75-12 w6m

Description: Vertical Separator

UTS Drawing#: 2

Item	N/A	Condition	Comment	NCR	Action Item Integrity	Action Item Maintenance
Nameplate		Good				
Foundation and Supports		Good				
Anchor Bolts	X					
Grounding			Could not locate ground cable.			
Insulation Condition	X					
PSV		Good				
Shell Heads and Nozzles		Good				
Metal Surfaces (Paint)		Good				
Aux Equipment	X					
Cathodic Protection	X					
Alignment		Good				
Flange Connections		Good				
Pressure Gauge		Good	0 to 200 psi			
Temperature Gauge		Good	-40 to 70°C			
Sight Glass		Good				
Ladder / Platform	X					
Leaks		None				
Piping from Vessel		Good				
Previous UT Survey	X					

External Visual Observations:

Vessel was not in service at the time of inspection.

Recommendations:

None at this time.

This vessel and associated components appear fit for service at this time.

INSPECTED BY
 LANCE SMITH
 API 510 #28860