



Pressure Vessel  
External Visual  
Inspection Report

Report #: **EV\_A 422134\_nov2011**  
 Inspection Date: **Nov 22, 2011**  
 Inspection Company: **Lance Inspections Inc.**  
 Inspector: **Lance Smith**

LSD: 10-08-74-10 w6m

Description: Vertical Separator

UTS Drawing#: 1

Item	N/A	Condition	Comment	NCR	Action Item Integrity	Action Item Maintenance
Nameplate		Good				
Foundation and Supports		Good				
Anchor Bolts		Good				
Grounding		Good				
Insulation Condition	X					
PSV		Good				
Shell Heads and Nozzles		Good				
Metal Surfaces (Paint)		Good				
Aux Equipment	X					
Cathodic Protection	X					
Alignment		Good				
Flange Connections	X					
Pressure Gauge		Good	0 to 200 psi			
Temperature Gauge		Good	-40 to 70°C			
Sight Glass		Good				
Ladder / Platform	X					
Leaks		None				
Piping from Vessel		Good				
Previous UT Survey	X					

External Visual Observations:

Vessel not in service at the time on inspection.

Recommendations:

None at this time.

This vessel and associated components appear fit for service at this time.

INSPECTED BY  
 LANCE SMITH  
 API 510 #28860