



Mountain West Services Ltd.

Inspection Report - CNRL # 7709

[\[www.mtnwest.ca\]](http://www.mtnwest.ca) [\[Company Index Page\]](#) [\[Vessels\]](#) [\[Pipelines\]](#) [\[SMART\]](#) [\[Incidents\]](#) [\[Work Orders\]](#) [\[Management of Change\]](#)

244015- LINE HEATER

VT External

Province:	Alberta	Manway:	NO
District:	GPOU	Coating:	No
Location:	MONTNEY	Inspect Date:	11/30/2006
LSD:	13-19-073-10W6	Inspection Interval:	60
CRN:	E-9866.213	Next Inspection:	11/30/2011
Skid/Equipment Number:	SKID0252	MAWP:	3136 PSI 21622.0928 KPa
Service:		Temperature:	1500 F 815.56 C
Status:	In Service	Outstanding NCRs:	0

General:

Safety Valves:

PSV [ANON-CODE](#) Protects the Coil1 Of the Vessel. Set Pressure of 5 PSI / 34.474 KPa. Capacity: /
 PSV [ANON-CODE](#) Protects the Coil2 Of the Vessel. Set Pressure of 5 PSI / 34.474 KPa. Capacity: /
 PSV [ANON-CODE](#) Protects the Shell Of the Vessel. Set Pressure of 5 PSI / 34.474 KPa. Capacity: /

Status: In Service	Examination Methods: VT	Access: External	Cleaning: Good
---------------------------	--------------------------------	-------------------------	-----------------------

External:

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical bonding, insulation and cladding appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. No evidence of short studding or nut rounding at time of inspection. Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has Alberta CRN and A# stamping, PSV has correct code stamp, set pressure and MWS tagging, and was last serviced within the required interval guidelines. Assign inspection interval.

Internal:

Recommendations:

<p>Inspector's Declaration: I have witnessed the above inspections and certify that they have been done in accordance with our manual and that the information is accurate. I certify that the status of the pressure equipment detailed here is:</p>
--

Suitable to be returned to service: Yes	Repairs complete: N/A
--	------------------------------

Repairs are still required: No	Suggested Inspection Interval: 60
---------------------------------------	--

Inspector: Glenn Allen, MWS	Date: 9/23/2007
------------------------------------	------------------------

<p>Chief Inspector: I certify that the information on this report is true and that all inspections required by the Owner/User Quality Assurance Program# AQP-8047 which expires in 12/06/05 have been done.</p>
--

Chief Inspector: Jim Damiani Cert 00037	
--	--

Date: 9/30/2007	
------------------------	--

[\[Back To Start Page\]](#) [\[MtnWest.Ca\]](#)