

Mountain West Services Ltd.

#3, 14 Thevenaz Industrial Trail, Sylvan Lake, AB T4S 2J5

Field Inspection Report - CNRL 194887_2/23/2012_VT_External

Vessel Number	194887	Vessel Name	SEPARATOR	Province	Alberta
District	WEST COUNTY	LSD	11-33-073-09W6	Location	VALHALLA
Method	VT	Access	External	Cleaning	Good
Inspection Date	2/23/2012	Inspection Interval	36	Next Inspection	2/23/2015
CRN	F-6669.2	Skid Number	SKID0211	Service	Sour
Manway	NO	Coating	False	Status	In Service
MAWP (PSI)	1376	MAWP (Kpa)	9487.24		
MAWT (F)	82.22	MAWT (C)	180	Outstanding NCRS	0

General

Safety Valves

PSV MWS64109 Shell side. Set pressure 1376 PSI / 3605 KPa. Capacity: 3605 SCFM / 102.08 m3/min.


External

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical bonding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. PSV is set at the correct PSI and has been serviced.

Internal

Recommendations

INSPECTOR : I have witnessed/done the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate. I certify that the status of the Pressure equipment detailed here is:

Suitable to be returned to Service	Yes	Repairs complete (AB-40 attached)	N/A
Repairs are still required	No	Suggested Inspection interval	36
Warren Fast Inspector			2/26/2012 Date



ADAX

ENERGY SERVICES LTD.
CALGARY, ALBERTA

ISP NO.

194387

ESSEL TYPE

CHALE VERTICIL BEE

ES. PRESS.

94.00

k.Pa.

82

°C

TEMP

147.0

PSI.

180

°F

EST PRESS

142.4

k.Pa.

3.2

mm.

C.A.

100.4

PSI.

125

IN.

HELL THK.

11.0

mm.

482650

k.Pa.

T.S.

1.175

IN.

70000

PSI.

11.0 MIN

mm.

482650

k.Pa.

1.012 MIN

IN.

70000

PSI.

1.012

CODE PARA

UW 12 A 83

W

X-RAY

11 1

PW.H.T.

YES

SER. NO.

12-11-V4000

C.R.N.

1-000000.2



