

Mountain West Services Ltd.

Box 7, Site 12, RR#1 DeWinton, AB T0L 0X0

Non-Conformance Report - CNRL# 155

Vessel:	139682
Equipment #:	
LSD:	08-34-073-10W6
Tag:	

Description of Non-Conformity:Damage
PSV Seal is broken and PSV is missing service tag.

Warren Fast	2/26/2012
Name	Date

Proposed Action/Disposition:
PSV needs to be serviced.
Further Action Required: True

_____	_____
Q.C Inspector & Date	Chief Inspector Date

Remedial Action: Repair

Action:

_____	_____	_____
Q.C Inspector & Date	Chief Inspector & Date	ABSA Inspector & Date

Corrective Action if Applicable:

