

Mountain West Services Ltd.

#3, 14 Thevenaz Industrial Trail, Sylvan Lake, AB T4S 2J5

Field Inspection Report - CNRL ST-C75988_3/4/2012_VT_External

Vessel Number	ST-C75988	Vessel Name	AST - ABOVE GROUND STORAGE	Province	Alberta
District	TEEPEE CREEK	LSD	04-35-074-08W6	Location	TEEPEE CREEK FIELD
Method	VT	Access	External	Cleaning	Good
Inspection Date	3/4/2012	Inspection Interval	36	Next Inspection	3/4/2015
CRN		Skid Number		Service	SOUR
Manway	No	Coating	False	Status	In Service
MAWP (PSI)	1	MAWP (Kpa)	6.89		
MAWT (F)	-17.78	MAWT (C)	0	Outstanding NCRS	0

General

Safety Valves

PSV P94032 Shell side. Set pressure 1 PSI / 0 KPa. Capacity: 0 SCFM / 0 m3/min.


External

All visible shell surfaces and nozzles appear in fair condition. Name plate is missing. Vessel supports, foundation, electrical bonding and external coverings appear fair. Associated piping, supports and components appear in good condition and alignment with no signs of leaks present at the time of inspection. PSV is set at correct PSI and has been serviced in the required interval.

Internal

Recommendations

INSPECTOR : I have witnessed/done the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate. I certify that the status of the Pressure equipment detailed here is:

Suitable to be returned to Service	Yes	Repairs complete (AB-40 attached)	N/A
Repairs are still required	No	Suggested Inspection interval	36
Warren Fast Inspector			3/9/2012 Date



