

Mountain West Services Ltd.

#3, 14 Thevenaz Industrial Trail, Sylvan Lake, AB T4S 2J5

Field Inspection Report - CNRL 414803_3/4/2012_VT_External

Vessel Number	414803	Vessel Name	SEPARATOR	Province	Alberta
District	TEEPEE CREEK	LSD	12-25-074-08W6	Location	TEEPEE CREEK FIELD
Method	VT	Access	External	Cleaning	Good
Inspection Date	3/4/2012	Inspection Interval	36	Next Inspection	3/4/2015
CRN	L-8282.21	Skid Number	SKID0595	Service	Sour
Manway	NO	Coating	False	Status	In Service
MAWP (PSI)	1440	MAWP (Kpa)	9928.51		
MAWT (F)	54.44	MAWT (C)	130	Outstanding NCRS	0

General

Safety Valves

PSV MWS68158 Shell side. Set pressure 1440 PSI / 5093 KPa. Capacity: 5093 SCFM / 144.22 m3/min.


External

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical bonding and external coverings appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks present at the time of inspection. PSV is set at correct PSI and has been serviced in the required interval.

Internal

Recommendations

INSPECTOR : I have witnessed/done the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate. I certify that the status of the Pressure equipment detailed here is:

Suitable to be returned to Service	Yes	Repairs complete (AB-40 attached)	N/A
Repairs are still required	No	Suggested Inspection interval	36
Warren Fast Inspector			3/10/2012 Date





UVL ID#: 53918G

S/N 40820-83

Man: TAYLOR

Model: 82E8351311

Set Press: 1415 PSI

Capacity: 5093 SCFM

Cold Diff:

Back Press: PSI

Size:

X 1" FNPT

AB:

Vessel SN:

WOR: 518530

PO Line#

POB:

REVISION 2 5-24-08 GP-001